

464043

[4910-13-P]

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

DEPARTMENT OF TRANSPORTATION
DOT/FAA

2007 APR -3 A 10:03

14 CFR Part 39

27714-3

[Docket No. FAA-2007-XXXXX; Directorate Identifier 2006-NM-277-AD]

RIN 2120-AA64

Airworthiness Directives; BAE Systems (Operations) Limited Model BAe 146 and Avro 146-RJ Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.**ACTION:** Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

There have been occurrences where a grille has become detached during flight. There is a risk that a loose grille could foul the rudder pedals and interfere with rudder/brake control resulting in an unsafe condition.

The unsafe condition is a rudder restriction or jam which could result in reduced controllability of the airplane. The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by [insert date 30 days after date of publication in the FEDERAL REGISTER].

CONCURRENCES
ROUTING SYMBOL ANM116TT(CR)
INITIALS/SIGNATURE [Signature]
DATE 4/23/07
ROUTING SYMBOL BOB ANM116B
INITIALS/SIGNATURE [Signature]
DATE 2/24/07
ROUTING SYMBOL [Signature]
INITIALS/SIGNATURE
DATE
ROUTING SYMBOL -7
INITIALS/SIGNATURE LG
DATE 3/14/07
ROUTING SYMBOL -114
INITIALS/SIGNATURE [Signature]
DATE 3/21/07
ROUTING SYMBOL -101
INITIALS/SIGNATURE [Signature]
DATE 3/21/2007
ROUTING SYMBOL -100
INITIALS/SIGNATURE [Signature]
DATE 3/21/07
ROUTING SYMBOL
INITIALS/SIGNATURE
DATE